

### 203.10 - Reference Points (solid forms)

These moderate purity SRMs are for use in preparing reference point devices and for calibrating thermometers, thermocouples and other temperature measuring devices.

Technical Contact: [gregory.strouse@nist.gov](mailto:gregory.strouse@nist.gov)

PLEASE NOTE: The tables are presented to facilitate comparisons among a family of materials to help customers select the best SRM for their needs. For specific values and uncertainties, the certificate is the only official source.

SRM	Description	Unit of Issue	Temperature (in oC)
45d	Cu Freezing Point	450 g	1084.8
49e	Lead Freezing Point	600 g	327.45
742	Alumina (Reference Point)	10 g	2052